


CORNER RECORD

BK 88 PG 48Document Number CR 9054City of FREMONT

County of _____, California

Brief Legal Description PART OF PORTION AS SHOWN NORTHWEST CORNER OF TRACT 5769**CORNER TYPE**

Government Corner	<input type="checkbox"/>	Control	<input type="checkbox"/>
Meander	<input type="checkbox"/>	Property	<input checked="" type="checkbox"/>
Rancho	<input type="checkbox"/>	Other	<input type="checkbox"/>

Date of Survey _____

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NADV88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


USED THE TRACT MAP 579 FOR BASIS OF BEARING BETWEEN THE FOUND CITY MONUMENTS
IN LOWRY ROAD SURVEYED FREEWAY SOUND WALL AND EXISTING FENCES. SET MONUMENTS
USING DISTANCES FOUND ON SAID MAP

A description of the physical condition of the monument as found and as set or reset: _____

FOUND 3/4 INCH IRON PIPE AT RECORD DISTANCE DOWN .10 FT IN RUSTY CONDITION BUT IN
THE CORRECT POSITION SET 5/8 INCH REBAR WITH BASS WASHER STAMPED L.S.6893

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on OCTOBER 4, 2016Signed Thomas C Gillett P.L.S. or R.C.E. No.: P.L.S. 6893**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received 10 OCTOBER, 2016 and examinedand filed 9 DECEMBER, 2016Signed Michael Rubner P.L.S. or R.C.E. No.: 6843Title COUNTY SURVEYOR

County Surveyor's Comment _____

