

CORNER RECORD


Bk 37 Pg 95

Document Number CR 4229

City of BERKELEY

County of ALAMEDA, California

Brief Legal Description CITY OF BERKELEY MONUMENT B2329



CORNER TYPE

Government Corner ☐ Control ☒
Meander ☐ Property ☐
Rancho ☐ Other ☐

Date of Survey MAY 28, 2010

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NADV88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND CHISELED CROSS WITH BRASS TACK

A description of the physical condition of the monument as found and as set or reset: FOUND MONUMENTS
IN GOOD CONDITION SET 4 NAILS WITH BRASS TAGS
AS REFERENCE POINTS. ALL SET TAGS L.S. NO. 5530
ALL POINTS SET IN CONCRETE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JUNE 25, 2010.

Signed Paul O. Webb P.L.S. or R.C.E. No.: PLS 5530

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-7-10 and examined
and filed 8-29-10

Signed Russell R. Penland P.L.S. or R.C.E. No.: 5726

Title COUNTY SURVEYOR

County Surveyor's Comment _____

